



Improvements / Changes of firmware 3.1
7817/7848/7849/7859/7817B/7848B/7849B/7859B/7869
February 2023

- ➔ Additions and support for SEFRAM 7869
 - ➔ Minor bug corrections
-

Improvements / Changes of firmware 2.4
7817/7848/7849/7859/7817B/7848B/7849B/7859B
November 2021

- ➔ Minor bug corrections
-

Improvements / Changes of firmware 2.3
7817/7848/7849/7859/7817B/7848B/7849B/7859B
March 2021

- ➔ Minor bug corrections
 - ➔ Improvement of measurement plan for German cable
-

Improvements / Changes of firmware 2.2
7817/7848/7849/7859/7817B/7848B/7849B/7859B
September 2020

- ➔ Minor bug corrections
Power supply for Optical LNB added with RF input (only 7859B)
-

Improvements / Changes of firmware 1.5
7817/7848/7849/7859
February 2018

- ➔ Improvement of remote supply current measurement
- ➔ Improvement of factory default parameters
- ➔ Minor bug correction



Important reminder : before updating the internal firmware, please be sure to save your instrument setup.

Improvements / Changes of firmware 1.3 7817/7848/7849/7859 June 2017 (v1.4) & December 2016 (v1.3)

- ➔ Improvement of the speed of satellite alignment (pointer)
 - ➔ Improvement of remote supply current measurement
 - ➔ 7859 with optical input
 - ➔ Minor bug correction
-

Improvements / Changes of firmware 1.2 7848/7849 April 2016

- ➔ Auto power-off added on home page
 - ➔ Minor bug correction
-

Improvements / Changes of firmware 1.1 7848/7849 November 2015

- ➔ Confirmation message added when importing a setup from USB
- ➔ Minor bug correction

Important reminder : before updating the internal firmware, please be sure to save your instrument setup.